
大葉大學九十二學年度 研究所碩士班 招生考試試題紙									
系 所	組別	考試科目(中文名稱)	考 試日 期	節次	備 註				
機械工程研究所碩士班	乙組	應用力學 或 機械製造	4月13日	第三節	• Casio 3600 功能 (含)以下計算機 • 不可使用鉛筆 • 共兩頁(P2-1)				

- 註: 考生可否攜帶計算機或其他資料作答,請在備註欄註明。
 - •以下共十題,請任選五題作答;屬第一頁之題目者,地表面之重力場強度 g = 9.81 m/s², 並請詳列計算步驟,否則一概不計分。(答題數不可超過 5 題,第6 題(含)以上不予計分)
- 1. Three parallel bolting forces act on the rim of the circular cover plate in Fig. 1. Determine the magnitude and direction of a resultant force equivalent to the given force system and locate its point of application, P, on the cover plate. (20%)
- 2. Determine the tension in cables BC and BD and the reactions at the ball-and-socket joint A for the mast sown in Fig. 2. (20%)
- 3. The maximum tension that can be developed in the cord shown in Fig. 3 is 500 N. If the pulley at A is free to rotate and the coefficient of static friction at the fixed drums B and C is $\mu_s = 0.25$, determine the largest mass of the cylinder that can be lifted by the cord. Assume that the force T applied at the end of the cord is directed vertically downward, as shown. (20%)
- 4. The 100-kg block A shown in Fig. 4 is released form rest. If the masses of the pulleys and the cord are neglected, determine the speed of the 20-kg block B in 2 s. (20%)
- 5. The uniform slender pole shown in Fig. 5 has a mass of 100 kg and a moment of inertia $I_G = 75 \,\mathrm{kg \cdot m^2}$. If the coefficients of static and kinetic friction between the end of the pole and the surface are $\mu_s = 0.3$ and $\mu_k = 0.25$, respectively, determine the pole's angular acceleration at the instant the 400-N horizontal force is applied. The pole is originally at rest. (20%)



大葉大學 九十二 學年度 研究所碩士班 招生考試試題紙								
系 所 別	組別	考 試 科 目 (中文名稱)	考 試 日 期	節次	備註			
機械工程研究所 碩士班	乙組	應用力學或機械製造	4月13日	第三節	, 开展百(P2-2)			

註:考生可否攜帶計算機或其他資料作答,請在備註欄註明(如未註明,一律不准攜帶)

- 6.請詳細描述如何從 n-type 矽晶片上,製造出一個局部的 p-type 區域,使成為一個 pn 二極體(Diode)的製程步驟?(20%)
- 7.請分析比較雷射束銲(Laser Beam Welding)、電子束銲(Electron Beam Welding)及電離子氣電弧銲(Plasma Arc Welding)之相關設備及製程特色?(20%)
- 8.對材料施以冷沖壓(Cold Forming)製程時,需考量那些重要因素?若利用此法對塑膠材料進行加工成型,則較它種成型方式的優點為何?(20%)
- 9.進行鑄造時,熔融金屬液的那些特性會影響澆鑄時的流動性(Fluidity)?並加以 說明。(20%)
- 10.對工件進行多餘部分的移除時,常需使用各種類型的切削工具(Cutting Tool),請問一般之切削工具應具有那幾種特性?並舉出六種常作為切削工具的材料?(20%)